INSPECTION REPORT

F	Partial <u>XXX</u>	_Comple	eteExp	loration
Inspection Date:	02/12/2003	/ Time:	10:00a.m.	to 12:00p.m.
-	Date	of Last I	nspection:	01/23/2002

Mine Name: <u>Hidden Valley Mine</u> County: <u>J</u>	Emery Permit Number: <u>C/015/007</u>		
Permittee and/or Operator's Name: Consolidation Coal Company			
Business Address: P.O. Box 566, Sesser IL 62	2884/P.O. Box 527, Emery, Utah 84522		
Company Official(s): Seth McCourt, James Byers,	Tim Kirschbaum, Ervin Anderson		
State Official(s): Joe Helfrich	Federal Official(s): None		
Weather Conditions: Overcast, 40	.,		
Type of Mining Activity: Underground XXX S	Surface Prep Plant Other		
Existing Acreage: Permitted 960 Disturbed 7 Regraded Seeded Seeded			
Status: Active	-		

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]	\Box	[X]	\Box
3.	TOPSOIL	\Box	\Box	\Box	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS		\Box	\Box	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS		[X]	\Box	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	
d.	WATER MONITORING	\Box	\Box	\Box	\Box
e.	EFFLUENT LIMITATIONS	\Box	[X]	\Box	\Box
5.	EXPLOSIVES		[X]		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[X] [X] [X]	\Box	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		\Box	\Box	
8.	NONCOAL WASTE				
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION		[X]	\Box	
12.	BACKFILLING AND GRADING				
13.	REVEGETATION	[X]		[X]	
14.	SUBSIDENCE CONTROL		[X]	\Box	\Box
15.	CESSATION OF OPERATIONS	[X]			
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING		[X]	\Box	
b.	DRAINAGE CONTROLS		[X]		
17.	OTHER TRANSPORTATION FACILITIES		[X]		
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS		[X]	\Box	
19.	AVS CHECK (4 th Quarter- April, May, June)			\Box	
20.	AIR QUALITY PERMIT		[X]	\Box	
21.	BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT

(Continuation Sheet)

DEDI HELHI IDED	C 104 = 100 =	DAME OF DIGRECATION	00/10/0000
PERMIT NUMBER:	C/015/007	DATE OF INSPECTION:	02/12/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The reclamation permit was renewed on January 29, 2002 and expires January 30, 2007. There are no amendments pending. The purpose of this site visit was to conduct a partial inspection of the reclaimed and associated disturbed areas.

2. SIGNS AND MARKERS

Point of access signs and perimeter markers were correctly posted. The fence at the lower end of the property needs to be reset.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The berms and ditches along the road, disturbed area, and reclaimed area were in good repair and functioning properly at the time of this inspection. The silt fence below the "A" seam needs to be connected to the wire fence in several places. An additional layer of silt fence could be added to the center area to replace the deteriorated portion. It should be noted that the fence was functioning properly at the time of the inspection.

13. REVEGETATION

As noted in the previous inspection, forbs and grasses were still evident in the roughened areas. Ivie Creek was flowing at approximately 3 gallons per minute and frozen over in the shaded areas. Deer and elk have been feeding on the reclaimed area. The "B" seam area under went additional reclamation in 1997. The vegetation is evident in the roughened areas along the lower as well as the side slopes. Mr. Kirschbaum indicated that a vegetation assessment could probably be completed this year to determine if the remaining portion of the site should undergo the same treatment.

Inspector's Signature:			Date: February 13, 2003
1 0 -	Joseph C. Helfrich	#1	

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Tim Kirschbaum, Consol, Illinois
Seth McCourt, Consol, Emery
Price Field office
O:\015007.HID\Compliance\2003\P_0212.doc